

1/6



FIG. 1





FIG. 2



1005503 022612 208220 60550012

2/6

FIG. 3





FIG. 4





3/6

72

FIG. 5





FIG. 6



4/6



FIG. 7






FIG. 8



10065903, 1222002, 200201, 2005001



↓ ↓ ↓ ↓ ↓ ↓ ↓ ↓ ↓ ↓




A cross-sectional diagram of a mechanical assembly. A central component, labeled 36, has a rectangular top surface 38 and vertical side surfaces 40. It is positioned between two horizontal components, 42 on the left and 44 on the right. These three parts are held together by a bolt or screw, labeled 34, which passes through them. The entire assembly is mounted on a base, labeled 28, which features a recessed area 64. A bracket on the right side of the base indicates a section 20. Dashed lines represent hidden internal features of the assembly.

[illegible]

6/6

FIG. 11



1005503 022802 208220 E0658001